

7642 Winston Street, Burnaby British Columbia V5A 2H4 Telephone: (604) 420-4433 Fax: (604) 420-2685 www.nde.net

An ISO 9001 Company

Branch Locations & Representatives

Kuala Lumpur, Malaysia

Visual Welding Inspection

Our Visual Inspection Department



Stasuk Testing & Inspection Ltd. is a <u>CWB</u> approved CSA 178.1 qualified Welding Inspection Organization as well as <u>AWS</u> CAWI & CWI certified. We have performed visual welding inspection on bridges, cranes, buildings, piping, pressure vessels and machinery as well as coating inspections, adhesion and bond testing and dimensional verification services.

Our visual inspection team has extensive experience in all types of construction and manufacturing in today's busy world. We take pride in our policy of sharing information and experience with all critical persons involved on a project so that we can insure that nothing is ever overlooked or **simple solutions ignored.**



All our NDE technicians are certified to American Standard for Nondestructive Testing's (ASNT)

recommended practice SNT-TC-1A and/or to Canadian General Standard Board CAN 48.9712 (ISO 9712) as well as being CWB Visual Inspectors. We work with our clients in satisfying their NDE requirements in accordance with contractual documents, applicable



codes and specifications. These codes include those of ASME/ANSI, ASTM, API, AWS, CSA, AWWA and AREA. Stasuk Testing & Inspection Ltd. is certified by Canadian Welding Bureau (CWB) as a qualified Welding Inspection Organization.

" A good name to know when both quality and productivity are needed"

Our group of experienced visual and coating inspectors

cover inspection sites throughout B.C. and our NDE Technicians travel throughout the world to inspect and monitor key essential areas in all fields of industry.

With over 25 years of service you can count on our ethical and professional approach to all of our clients and projects.

STASUK TESTING & INSPECTION LTD.

